



City of Tacoma

Questions and Answers

34TH STREET BRIDGE DECK REPAIR

RFQ Specification No. PW23-0141F

All interested parties had the opportunity to submit questions in writing by email to Brandon Snow, Senior Buyer, by date questions were due. The answers to the questions received are provided below and posted to the City's website at www.TacomaPurchasing.org. Navigate to [Current Contracting Opportunities / Services Solicitations](#), and then click *Questions and Answers* for this Specification. This information IS NOT considered an addendum. Respondents should consider this information when submitting their proposals.

Question 1: Does this project have any plans?

Answer 1: The 2022 bridge inspection report, along with annotated 1935 plan drawings, a 2022 initial seismic and load rating deficiency evaluation, a 2022 WSBIS Local Agency Inventory Report, and photos of existing conditions, have been attached for reference.

The current annual bridge report is also available online:

<https://www.cityoftacoma.org/cms/One.aspx?portalId=169&pageId=206270>

(Select 'Annual Bridge Inspection Report' drop-down menu. Then select link to 'Current Annual Bridge Report'. Navigate to Bridge No. 28 34thP-A)

BRIDGE INSPECTION REPORT

Page 1 of 5

Status: Released
 CD Guid: f439ffb4-0148-4e4a-9910-ed839b882bca

Printed On: 4/25/2022
 Release Date: 4/21/2022

Agency: TACOMA
 Program Mgr: Sonia L. Lowry

Br. No. 28 34thP-A **SID** 08512200 **Br. Name** EAST 34TH STREET
Carrying EAST 34TH STREET **Route On** 03234 **Mile Post** 10.00
Intersecting PACIFIC TO A ST **Route Under** **Mile Post**

Inspector's Signature SJC Cert # G0315 Cert Exp Date 4/15/2026

Co-Inspector's Signature CDN

Inspections Performed

Report Type	Inspection Type	Date	Freq	Hours	Inspector	Cert No	Co-Insp.
Routine		6/17/2020	24	2.5	SJC	G0315	CNS
<u>Interim</u>		<u>4/4/2022</u>	<u>60</u>	<u>8.0</u>	<u>SJC</u>	<u>G0315</u>	<u>CDN</u>
<u>Informational</u>		<u>4/4/2022</u>			<u>SJC</u>	<u>G0315</u>	<u>CDN</u>

8	<input type="checkbox"/>	Alignment (1661)	36	<input type="checkbox"/>	Operating Tons (1552)	0	<input type="checkbox"/>	Bridge Rails (1684)	2	<input type="checkbox"/>	No Utilities (2675)
5	3	Deck Overall (1663)	1.01	<input type="checkbox"/>	Op RF (1553)	0	<input type="checkbox"/>	Transition (1685)	0.50	<input type="checkbox"/>	Asphalt Depth (2610)
5	<input type="checkbox"/>	Superstructure (1671)	21	<input type="checkbox"/>	Inventory Tons (1555)	0	<input type="checkbox"/>	Guardrails (1686)	1937	<input type="checkbox"/>	Year Built (1332)
5	<input type="checkbox"/>	Substructure (1676)	0.60	<input type="checkbox"/>	Inv RF (1556)	0	<input type="checkbox"/>	Terminals (1687)	0	<input type="checkbox"/>	Year Rebuilt (1336)
9	<input type="checkbox"/>	Culvert (1678)	5	<input type="checkbox"/>	Operating Level (1660)	44.5	<input type="checkbox"/>	Bridge Rail Ht (2612)			
9	<input type="checkbox"/>	Chan/Protection (1677)	P	<input type="checkbox"/>	Open/Closed (1293)	8.50	<input type="checkbox"/>	Design Curb Ht (2611)			
N	<input type="checkbox"/>	Pier/Abut/Prot (1679)	5	<input type="checkbox"/>	Structural Eval (1657)						
9	<input type="checkbox"/>	Waterway (1662)	2	<input type="checkbox"/>	Deck Geometry (1658)						
N	<input type="checkbox"/>	Scour (1680)	9	<input type="checkbox"/>	Underclearance (1659)						

NBIS Risk Category
Routine: Low Risk
Underwater: No Risk Category

Inspection Flags

N <input type="checkbox"/> Soundings (2693)	<input type="checkbox"/> Measure Clearance (2694)	N <input type="checkbox"/> Revise Rating (2688)	P D <input type="checkbox"/> Photos (2691)	<input type="checkbox"/> QA Flag (2695)
--	---	--	--	---

BMS Elements

Element	Element Description	Total	Units	CS 1	CS 2	CS 3	CS 4
12	Concrete Deck	11640	SF	10497	0	0	1143
35	Concrete Deck Soffit	11640	SF	10640	0	1000	0
110	Concrete Girder	1454	LF	1440	0	14	0
144	Concrete Arch	485	LF	485	0	0	0
150	Concrete Column on Spandrel Arch	28	EA	18	0	8	2
155	Concrete Floor Beam	648	LF	645	0	3	0
205	Concrete Pile/Column	20	EA	11	0	5	4
215	Concrete Abutment	160	LF	160	0	0	0
234	Concrete Pier Cap/Crossbeam	96	LF	96	0	0	0
266	Concrete Sidewalk & Supports	4850	SF	4517	0	333	0
310	Elastomeric Bearing	4	EA	0	0	4	0
311	Moveable Bearing (roller, sliding, etc)	4	EA	4	0	0	0
321	Concrete Roadway Approach Slab	768	SF	668	0	100	0
331	Concrete Bridge Railing	970	LF	950	20	0	0
370	Seismic - Longitudinal Restrainer	4	EA	4	0	0	0

BRIDGE INSPECTION REPORT

Page 2 of 5

Status: Released
CD Guid: f439ffb4-0148-4e4a-9910-ed839b882bca

Printed On: 4/25/2022
Release Date: 4/21/2022

Agency: TACOMA
Program Mgr: Sonia L. Lowry

Br. No. 28 34thP-A	SID 08512200	Br. Name EAST 34TH STREET
Carrying EAST 34TH STREET	Route On 03234	Mile Post 10.00
Intersecting PACIFIC TO A ST	Route Under	Mile Post

BMS Elements (Continued)

Element	Element Description	Total	Units	CS 1	CS 2	CS 3	CS 4
371	Seismic - Transverse Restrainer	8	EA	8	0	0	0
376	Concrete Deck Delamination Testing	11640	SF	10497	0	0	1143
402	Open Concrete Joint	48	LF	0	0	0	48
408	Steel Sliding Plate	96	LF	72	0	24	0
800	Asphaltic Concrete (AC) Overlay	11640	SF	7660	0	0	3980

Notes

- 0 The bridge orientation is west to east. The structure has 6 spans which are labeled 1 through 6. There are a total of 9 piers, which are labeled 1 through 9, from west to east.
Due to the complexity of the structure, it is advised to see the "2020 Inspector Layout Sheet" in the plans section of Bridgeworks.

Access to west abutment is through NW business parking area. There is a gate with a lock on it. Lock is currently frozen and should be replaced. Access to underside of bridge is south of 34th Street (12316 Pacific ave - Ahsleys Pipe Shop) via an access with a locked gate.

- 11 The bridge is posted for EV 3 vehicles and signs have been installed on the structure. The city has issued a permit for all impacted EV3 vehicles which allows those EV3's to still use the bridge if they adhere to the 10 MPH advisory speed limit.

- 12 The deck appears to be in poor condition. The caveat to this statement is most of the deck is covered in a failing chip seal and it is not visible to inspect. The chip seal is failing/failed on the deck. The deck is showing cracks, spalls, exposed reinforcing steel, and delaminations.

Specific deficiencies noted in the files tab along with mapping of locations and noted in BMS element 376.

- 35 The concrete deck soffit in span 1, 3, 5, and 6, appear to be in good condition. There are some minor cracking with leacheate.

The concrete deck soffit in span 2 appears to be in fair to good condition. There is a 1/2" crack in several locations with leacheate and rust staining as noted in the 2018 inspection.

The concrete deck soffit in span 4 appears to be in fair condition. The "spans" between spandrel columns 3 to 13 show evidence of transverse and longitudinal cracking. There is leaching and efflorescence show through these locations.

- 110 General girder deficiency note: All of the girders within the arch appear to have hairline leaching cracks with efflorescence. Some of the cracks appear to be near midspan of the girder. Many of these spalls and cracks have not appeared to have changed since previous inspections. Many of these deficiencies appear to be minor.

Span 1:

Girder 1, near pier 2 has a 6"x6" spall.

Girder 2, near pier 2 has 2 spall with exposed reinforcing steel on the bottom surface. Approximate size is 1'x1' each.

Girder 4, near pier 1 has a 5" long crack on the south face, approximately 1/8" wide.

Span 2:

Girder 4, near pier 2, has a 6"x6" spall.

Span 7:

Girder 1, north face, has an 8" spall the full height of the girder with 22" of exposed reinforcing steel.

Girder 3, north face, has 3 short sections of exposed reinforcing steel near midspan. There is also an exposed reinforcing steel near pier 8.

Span 8:

Girder 4, there is an exposed reinforcing steel 24" long, near pier 8.

BRIDGE INSPECTION REPORT

Page 3 of 5

Status: Released
CD Guid: f439ffb4-0148-4e4a-9910-ed839b882bca

Printed On: 4/25/2022
Release Date: 4/21/2022

Agency: TACOMA
Program Mgr: Sonia L. Lowry

Br. No. 28 34thP-A	SID 08512200	Br. Name EAST 34TH STREET
Carrying EAST 34TH STREET	Route On 03234	Mile Post 10.00
Intersecting PACIFIC TO A ST	Route Under	Mile Post

Notes (Continued)

144 Overall, the concrete arches appear to be in good condition.

There are a couple of minor deficiencies to note:

Arch 1 has a vertical leaching crack at the cold joint on the insdie face near spandrel column 2. There are also hairline diagonal cracks, 12" on center for approx. 10 feet, on the top of the arch between spandrel column 7 and 8.

150 Overall, the spandrel arch columns appear to be in fair condition. The spandrel columns appear to have areas of poor concrete consolidation, leaving many rock pockets. When the rock pockets spall, they leave exposed reinforcing steel.

Many of the spandrel columns have a crack all around the column at the top, where it connects to the girder.

SC1A is spalled at the bottom of the south face, and 24" high on the SEC. Three of the corners at the bottom of the column have spalls. There is a 12" spall in the NWC near the arch and a 10" x 6" spall, NWC, with exposed bar.

SC1B is spalled on the SWC, 32" high x 6" wide x 4" deep. There is 21" of exposed reinforcing steel.

SC2A has four spalls on the NW corner, with a total of 12" of exposed reinforcing steel. The lower 10 ft. of the NWC is all spalled.

SC2B has a crack in NEC at mid-height of column. This crack is forming into a spall.

SC3A SEC near the Arch has a 12" x 8" spall.

SC3B is spalled on the SEC (16" high x 3" wide x 2" deep) which has 12" of exposed reinforcing steel.

SC4A at the SWC support, there is 18" of exposed reinforcing steel.

SC8B, there is an 8" spall on the SWC with 4" of exposed reinforcing steel. The north face has cracking on the bottom half.

SC12A is spalled on the SEC. It has 18" of exposed reinforcing steel at the base, and 12" of exposed reinforcing near the lower third point of the column. This spall is approx. 12' high on the NEC. There are two reinforcing bars exposed at the base and 8' of exposed vertical reinforcing.

SC12B is spalled on the NW edge at the bottom at Arch B. There is a 6" spall at the base of the column.

SC13A has rock pockets near mid-height and a 14" x 4" x 2" deep spall with 11" of exposed reinforcing at the NEC. The spall on the SE C has 8" of exposed reinforcing at the base and 8" of exposed reinforcing near the one quarter height. There is also a spall on the SW edge and a spall and delamination on the NW edge at the construction joint. There is a crack at NW corner at mid-height. The crack is fully across the column face horizontally.

SC13B is spalled on the NW and SW corners, with 30" of exposed reinforcing.

SC14A is spalled on the SEC, 26" high x 4" wide x 2" deep, just above the mid-height strut. It has 18" of exposed reinforcing. There is approx. 10 ft. of rock pockets on this column. The NE and NW corners are spalled, with approx. 8' of exposed reinforcing at each.

155 Overall, the concrete floor beams are in good condition. Several of the floorbeams are exhibiting leaching cracks with effloresceanse.

Specific Deficiencies are: There are two exposed reinforcing steel, approx. 10" and 20" in length, in the west face of the Pier 6 floorbeam

BRIDGE INSPECTION REPORT

Page 4 of 5

Status: Released
 CD Guid: f439ffb4-0148-4e4a-9910-ed839b882bca

Printed On: 4/25/2022
 Release Date: 4/21/2022

Agency: TACOMA
 Program Mgr: Sonia L. Lowry

Br. No. 28 34thP-A	SID 08512200	Br. Name EAST 34TH STREET	
Carrying EAST 34TH STREET		Route On 03234	Mile Post 10.00
Intersecting PACIFIC TO A ST		Route Under	Mile Post

Notes (Continued)

205 There are four columns each, at Piers 2, 3, and 8, and two columns each at Piers 4, 5, 6, and 7. The concrete pile/columns appear to be in fair, to good, condition. Specific deficiencies are:

Column 3B, has a 5" spall with exposed reinforcing on the west face, just above the strut. On the east face, there is a 2 ft. x 1 ft. spall

Column 4A has three pieces of exposed reinforcing steel on the west face and three pieces on the south face, near midheight. There are 4 spalls on south face at bottom 10 ft. of the column. There is a 12" x12" spall with exposed reinforcing steel in the section. Column 4B has a 12" spall with exposed reinforcing on the west face, near the top. Column 5A, SE edge, has an 11" x 5" x 2" deep spall with exposed vertical reinforcing. It is located in the construction joint, at the strut, between Columns 5A and 5B. Column 5b has 18" of exposed vertical reinforcing on the north face at mid-height.

Column 7A has a crack at the sidewalk support.

215 The concrete abutments appear to be in good condition. There are small, minor blemishes evident on the faces of the abutments.

234 The crossbeams appear to be in good condition. There are some minor deficiencies at the top of the columns at Piers 4, 5, 6 and 7 which have vertical leaching cracks.

266 The concrete sidewalk supports appear to be in good condition. The sidewalk surface appears to be in fair to poor condition. There are signs of deficiencies in several locations.

Specific deficiencies noted in the files tab along with mapping.

A complete list of size and locations for spalls, delaminations, and cracking can be found in the Files Tab along with mapping of the locations. This was from chain dragging which occurred in March 2022 to document all of the deck and sidewalk deficiencies.

310 The elements we are noting as "elastomeric bearings" are really more like heavy asphalt material which may allow movement similar to a elastomeric bearing. This item is the most logical place for these elements.

The elastomeric bearings appear to be in fair to poor condition as noted in the 2018 inspection. Some of the material is deteriorated to a state which it can be easily broken off and removed from the wearing interface between the column and crossbeam. Due to this, all bearings are being put into CS3.

311 The moveable bearings appear to be in good condition and show no signs of deficiencies.

There are movable bearings at Pier 4 and Pier 7 at the top of the columns. These are sliding plates which appear to be in good condition and show no signs of deficiencies.

321 The concrete approach slabs are not visible during this inspection due to a chip seal overlay installed on the top of them. The portions which are visible show signs of surface wear, exposed aggregate, and small surface defects and spalls. The approach slab with this wear is accounted for in CS3.

The chip seal overlay appears to be in poor condition and has failed. This amount of poor/failed chip seal is accounted for in element #800.

331 The concrete bridge rails appear to be in good condition and show no signs of deficiencies. Note, a 20 ft. segment near midspan, south side was removed and replaced due to a car accident. This accounts for the amount of rail in CS2.

370 The longitudinal restrainers appear to be in good condition and show no signs of deficiencies.

371 The transverse restrainers appear to be in good condition and show no signs of deficiencies.

376 Specific deficiencies noted in the files tab along with mapping.

A complete list of size and locations for spalls, delaminations, and cracking can be found in the Files Tab along with mapping of the locations. This was from chain dragging which occurred in March 2022 to document all of the deck and sidewalk deficiencies.

402 The open concrete joints in the bridge deck have all failed and no longer function.

BRIDGE INSPECTION REPORT

Page 5 of 5

Status: Released
 CD Guid: f439ffb4-0148-4e4a-9910-ed839b882bca

Printed On: 4/25/2022
 Release Date: 4/21/2022

Agency: TACOMA
 Program Mgr: Sonia L. Lowry

Br. No. 28 34thP-A	SID 08512200	Br. Name EAST 34TH STREET
Carrying EAST 34TH STREET	Route On 03234	Mile Post 10.00
Intersecting PACIFIC TO A ST	Route Under	Mile Post

Notes (Continued)


- 408 The steel plates are working loose and make a loud noise when a vehicle passes. These plates have been repaired several times by Tacoma crews, but need further attention. 2018, The sliding plate on pier 5 has been removed. The westbound lane header is spalling from impact loads.
- 800 The chip seal over the roadway is in poor condition. It has worn away in the wheel paths. Note, 100 SF of failed AC overlay comes from the chip seal on the concrete approach roadway slabs on either end as noted in element ID 321.
- 1663 In April 2022, the city performed a delamination check of the deck and sidewalks. Due to the amount of delamination found (9.4% deck) BMS element 1663 was changed from a 5 to a 3. This was a change also recommended by WSDOT.

Repairs

Repair No	Pr	R	Repair Descriptions	BMS	Noted	Maint	Verified
10005	M	B	resurface concrete deck with a concrete overlay	12	6/17/2020		
10006	M	B	patch all spalls and exposed reinforcing steel of the superstructure	110, 150, 155, 205	6/17/2020		
10007	M	B	repair or replace all bearings	310, 311	6/17/2020		
10008	M	B	replace concrete approach slabs	321	6/17/2020		
10009	3	B	remove vegetation from under the bridge, in the gulch for easier access prior to next inspection.	0	6/17/2020		
10010	3	B	replace lock on west side abutment access next to business. The existing lock is frozen.	0	6/17/2020		
10011	M	B	repair sidewalk spalls and exposed reinforcing steel	266	6/17/2020		
10012	M	B	repair/replace failed expansion joints	408	6/17/2020		

Inspections Performed and Resources Required


Report Type	Date	Freq	Hrs	Insp	CertNo	Coinsp	Note		
Routine	6/17/2020	24	2.5	SJC	G0315	CNS	2020 routine inspection		
Resources	Hours	Min	Pref	Max	Freq	Date	Need Date	Override	Notes
UBIT	3.00	30	60	60					SDOT UBIT was used for 2016 inspection
UBIT	8.00	30	60	60					SDOT UBIT was used for 2010 inspection.
UBIT	3.50	30	60	60					UB60 used for 2008 inspection. The UB50 and UB30 will require deployment off both sides.
Flagging	4.00	LA	LA	LA					Contact Steve Carstens at 253.591.5263 to arrange for flagging.
Interim	4/4/2022	60	8.0	SJC	G0315	CDN	interim inspection performed to verify amount of delamination in deck and sidewalks.		
Informational	4/4/2022			SJC	G0315	CDN	informational to insert new deck delamination information.		



34TH Street P-A Deck Delaminations

	Sta	Offset	R/L	L	W	SF
Approach slab	511	3	L	9	12	108
Approach slab	511	6	R	2	11	22
Deck/Spall	500	4	R	2	4	8
Deck/Spall	485	4	R	9	12	108
Deck/Spall	475	4	R	2	3	6
Deck/Spall	465	11	R	2	3	6
Deck/Spall	450	5	L	2	3	6
Deck/Spall	450	5	R	1	4	4
Deck/Spall	420	4	L	1	3	3
Deck/Spall	380	12	R	3	3	9
Deck/Spall	350	3	L	5	8	40
Deck/CRACK	340	NA	NA	1	24	24
Deck/CRACK	330	NA	NA	1	24	24
Deck/CRACK	317	NA	NA	1	24	24
Deck/Spall	290-310	5	L	4	20	80
Deck/CRACK	290	NA	NA	1	24	24
Deck/CRACK	275	NA	NA	1	24	24
Deck/CRACK	260	NA	NA	1	24	24
Deck/CRACK	250	NA	NA	1	24	24
Deck/CRACK	230	NA	NA	1	11	11
Deck/Spall	210	7	R	2	3	6
Deck/Spall	190-234	7	L	2	44	88
Deck/Spall	190	2	R	10	10	100
Deck/Spall	170	4	R	1	2	2
Deck/Spall	150	4	L	5	7	35
Deck/Spall	130	4	L	2	3	6
Deck/Spall	120-142	2	R	3	22	66
Deck/Spall	125	4	R	2	3	6
Deck/Spall	125	10	R	2	2	4
Deck/Spall	115	7	L	1	1	1
Deck/Spall	100	5	R	4	2	8
Deck/Spall	100	3	L	2	6	12
Deck/Spall	85	4	L	11	2	22
Deck/Spall	85	3	R	2	3	6
Deck/Spall	75	2	L	2	2	4
Deck/Spall	75	4	R	1	9	9
Deck/Spall	50	0	NA	9	9	81
Deck/Spall	15	1	R	3	10	30
Approach slab	5	1	L	2	3	6
				Total (SF)		1071

34P-A Bridge #08512200



NOTE: 0+00 is Mon. at East 34th Str. and Pacific Ave.

Extra Handrail Change No.2

Span 1 span 2 span 3 span 4 span 5 span 6

abut 1 pier 2 pier 3 pier 4 pier 5 pier 7 pier 8

Expansion Joint

Poor Confinement, Ductility Deficiency

Tie-Beams, Poor confinement, Ductility deficiency

15 Spans @ 15.5' = 232.5'

Ground on & Ground - 20' North of & Ground - 20' South of &

Rad. 174 Rad. 174 Rad. 174

looking north

ELEVATION Scale 1"=20'

NOTE: 0+00 is Mon. at East 34th Str. and Pacific Ave.

Extra Handrail Change No.2

Span 1 span 2 span 3 span 4 span 5 span 6

abut 1 pier 2 pier 3 pier 4 pier 5 pier 7 pier 8

Expansion Joint

Poor Confinement, Ductility Deficiency

Tie-Beams, Poor confinement, Ductility deficiency

15 Spans @ 15.5' = 232.5'

Ground on & Ground - 20' North of & Ground - 20' South of &

Rad. 174 Rad. 174 Rad. 174

looking north

ELEVATION Scale 1"=20'

NOTE: 0+00 is Mon. at East 34th Str. and Pacific Ave.

Extra Handrail Change No.2

Span 1 span 2 span 3 span 4 span 5 span 6

abut 1 pier 2 pier 3 pier 4 pier 5 pier 7 pier 8

Expansion Joint

Poor Confinement, Ductility Deficiency

Tie-Beams, Poor confinement, Ductility deficiency

15 Spans @ 15.5' = 232.5'

Ground on & Ground - 20' North of & Ground - 20' South of &

Rad. 174 Rad. 174 Rad. 174

looking north

ELEVATION Scale 1"=20'

NOTE: 0+00 is Mon. at East 34th Str. and Pacific Ave.

Extra Handrail Change No.2

Span 1 span 2 span 3 span 4 span 5 span 6

abut 1 pier 2 pier 3 pier 4 pier 5 pier 7 pier 8

Expansion Joint

Poor Confinement, Ductility Deficiency

Tie-Beams, Poor confinement, Ductility deficiency

15 Spans @ 15.5' = 232.5'

Ground on & Ground - 20' North of & Ground - 20' South of &

Rad. 174 Rad. 174 Rad. 174

looking north

ELEVATION Scale 1"=20'

NOTE: 0+00 is Mon. at East 34th Str. and Pacific Ave.

Extra Handrail Change No.2

Span 1 span 2 span 3 span 4 span 5 span 6

abut 1 pier 2 pier 3 pier 4 pier 5 pier 7 pier 8

Expansion Joint

Poor Confinement, Ductility Deficiency

Tie-Beams, Poor confinement, Ductility deficiency

15 Spans @ 15.5' = 232.5'

Ground on & Ground - 20' North of & Ground - 20' South of &

Rad. 174 Rad. 174 Rad. 174

looking north

ELEVATION Scale 1"=20'

INDEX	
Sheet No. ①	General Plan & Elevation
" " ②	Longitudinal Section of Arch Span
" " ③	Approach Girder Spans
" " ④	Arch Piers
" " ⑤	Profiles at Piers
" " ⑥	Columns & Bents for Approaches
" " ⑦	Longitudinal Girders for
" " ⑧	Miscellaneous Details
" " ⑨	Expansion Joint Details
" " ⑩	Hand Rail Detail
" " ⑪	Abutments & Retaining Walls
" " ⑫	Concrete Pouring Diagram
" " ⑬	Plan & Details-Bridge Entrances
" " ⑭	Ornamental Lighting

Drawing LL-120

Construction Field Books:-

1553 - Cross-sections of excava., et c.

1554 - Misc.

1555 - Pile driving for falsework - Const. Log

1561 -

1562 - Field Party's misc. notes


SURVEY: FIELD BOOK No. 1517.

CITY OF TACOMA - DEPT. OF PUBLIC WORKS DIVISION OF ENGINEERING		
BRIDGE No. E-7 EAST 34 th STREET - PACIFIC AVE TO A STR. GENERAL PLAN & ELEV.		
DESIGNER D.A.A. MAKER D.A.A. TRACER D.A.A. CHECKER REVISIONS	APPROVED: <i>[Signature]</i> CITY ENGINEER COMMISSIONER OF PUBLIC WORKS <i>[Signature]</i> Bridge Engineer	DATE: OCT-15-1935 SCALE: As Noted Sheet 1 of 14 Sheets

Seismic parameters

Based on the bridge coordination and site class B, the design response spectrum is:

Seismic Design Category (SDC) = B



$$C_{sm} := 0.84$$

We assume that expansion joints have been connected using a link-slab system. In this case, spandrel columns are more vulnerable in the transverse direction. Using a simplified approach and considering the mass based on the tributary area, the seismic moment and shear are calculated as follows:


FRP layers to enhance confinement at top and bottom of the columns

$$W_{Deck} := 9.35 \frac{\text{kip}}{\text{ft}}$$

Column 3:

$$C3_A := (1 \text{ ft} + 8 \text{ in})^2 = 400 \text{ in}^2$$

$$HCol_3 := 25 \text{ ft} + 8 \text{ in}$$



$$EQ_3 := Csm \cdot \left(\frac{W_{Deck}}{2} \cdot 15.5 \text{ ft} + C3_A \cdot HCol_3 \cdot 0.155 \frac{\text{kip}}{\text{ft}^3} \cdot 0.5 \right) = 65.51 \text{ kip}$$

$$M_{C3} := \frac{EQ_3 \cdot HCol_3}{2} = 840.71 \text{ kip} \cdot \text{ft}$$

$$As := 3 \cdot 0.79 \text{ in}^2 \quad 3\text{-}\#8$$

$$Fy := 40 \text{ ksi}$$

$$ds := 1 \text{ ft} + 8 \text{ in} - 2 \text{ in}$$

$$f'c := 4 \text{ ksi}$$

$$b := 1 \text{ ft} + 8 \text{ in}$$

$$Mp := 1.10 \cdot \left(As \cdot Fy \cdot \left(ds - 0.5 \cdot \frac{As \cdot Fy}{0.85 \cdot f'c \cdot b} \right) \right) = 150.363 \text{ kip} \cdot \text{ft}$$

$$\frac{M_{C3}}{Mp} = 5.591$$

The ratio of elastic demand to plastic capacity is more than 5.0. It means a significant plastic curvature is expected at the top and bottom of the spandrel columns. Good confinement is needed to avoid concrete degradation and buckling of the longitudinal/vertical bars. Currently, ties are provided at 12-inch spacing. This spacing does not meet the code minimum requirement for tie spacing. Therefore, 4-6 layers of FRP are expected to achieve desirable confinement at this location.

Subject: Initial Seismic and load rating deficiencies

evaluation

Column 2:

$$C2_A := (1 \text{ ft} + 8 \text{ in})^2 = 400 \text{ in}^2$$

$$HCol_2 := 36 \text{ ft}$$

$$EQ_2 := Csm \cdot \left(\frac{W_Deck}{2} \cdot 15.5 \text{ ft} + C2_A \cdot HCol_2 \cdot 0.155 \frac{\text{kip}}{\text{ft}^3} \cdot 0.5 \right) = 67.379 \text{ kip}$$

$$M_C2 := \frac{EQ_2 \cdot HCol_2}{2} = 1213 \text{ kip} \cdot \text{ft}$$

$$\frac{M_C2}{Mp} = 8.066$$

Significant confinement enhancement using FRP is needed.

Column 6:

$$C6_A := (1 \text{ ft} + 8 \text{ in})^2 = 400 \text{ in}^2$$

$$HCol_6 := 7.5 \text{ ft}$$

$$EQ_6 := Csm \cdot \left(\frac{W_Deck}{2} \cdot 15.5 \text{ ft} + C6_A \cdot HCol_6 \cdot 0.155 \frac{\text{kip}}{\text{ft}^3} \cdot 0.5 \right) = 62.225 \text{ kip}$$

$$M_C6 := \frac{EQ_6 \cdot HCol_6}{2} = 233 \text{ kip} \cdot \text{ft}$$

$$\frac{M_C6}{Mp} = 1.552$$

Minimum confinement enhancement is expected for shorter columns

Subject: Initial Seismic and load rating deficiencies

evaluation

Columns at approach spans


Rocking in the longitudinal direction is expected considering the width of the bent footing. However, columns can experience a significant moment at the top and bottom in the transverse direction. Here, the behavior of the bent in the transverse direction is considered.

$$H_a := 48 \text{ ft}$$

$$b_{top} := 2 \text{ ft}$$

$$b_{bot} := 2.5 \text{ ft}$$

$$W := 1.5 \text{ ft}$$



$$W_{App} := 393 \text{ kip} + 4 \cdot W \cdot \left(\frac{b_{top} + b_{bot}}{2} \right) \cdot \frac{H_a}{2} \cdot 0.155 \frac{\text{kip}}{\text{ft}^3} + 2.5 \text{ ft} \cdot 1.5 \text{ ft} \cdot 6.5 \text{ ft} \cdot 0.155 \frac{\text{kip}}{\text{ft}^3} \cdot \frac{3}{2}$$


$$W_{App} = 449 \text{ kip}$$

$$EQ_a := Csm \cdot W_{App} = 377 \text{ kip}$$

$$M_{Ca} := \frac{\frac{EQ_a}{4} \cdot H_a}{2} \cdot 0.75 = 1697 \text{ kip} \cdot \text{ft}$$

Subject: Initial Seismic and load rating deficiencies

evaluation



$$A_{se} := 3 \cdot 0.79 \text{ in}^2 \quad 3\text{-}\#8$$

$$A_{si} := 4 \cdot 0.79 \text{ in}^2 \quad 4\text{-}\#8$$

$$F_y := 40 \text{ ksi}$$

$$d_s := W - 2 \text{ in} = 16 \text{ in}$$

$$f'_c := 4 \text{ ksi}$$

$$M_{p_{TE}} := 1.10 \cdot \left(A_{se} \cdot F_y \cdot \left(d_s - 0.5 \cdot \frac{A_{se} \cdot F_y}{0.85 \cdot f'_c \cdot b_{top}} \right) \right) = 133.992 \text{ kip} \cdot \text{ft}$$

$$M_{p_{BE}} := 1.10 \cdot \left(A_{se} \cdot F_y \cdot \left(d_s - 0.5 \cdot \frac{A_{se} \cdot F_y}{0.85 \cdot f'_c \cdot b_{bot}} \right) \right) = 135.002 \text{ kip} \cdot \text{ft}$$

$$M_{p_{TI}} := 1.10 \cdot \left(A_{si} \cdot F_y \cdot \left(d_s - 0.5 \cdot \frac{A_{si} \cdot F_y}{0.85 \cdot f'_c \cdot b_{top}} \right) \right) = 176.413 \text{ kip} \cdot \text{ft}$$

$$M_{p_{BI}} := 1.10 \cdot \left(A_{si} \cdot F_y \cdot \left(d_s - 0.5 \cdot \frac{A_{si} \cdot F_y}{0.85 \cdot f'_c \cdot b_{bot}} \right) \right) = 178.207 \text{ kip} \cdot \text{ft}$$

Comparing elastic moment demands with plastic capacities of interior and exterior columns shows that a plastic hinge is expected at the top and bottom of the columns in the transverse direction. So, an FRP strengthening to increase the ductility capacity of the columns is needed.

Link-Slab preliminary design

$$H_T := 2 \cdot (2 \cdot 293) \text{ ft} = 1172 \text{ ft} \quad \text{total length of columns}$$

$$W_T := \left(W_{Deck} \cdot (15.5 \text{ ft} \cdot 7.5 + 10 \text{ ft}) \cdot 2 + C3_A \cdot H_T \cdot 0.155 \frac{\text{kip}}{\text{ft}^3} \cdot 0.5 \right)$$

$$W_T = 2613.2 \text{ kip} \quad \text{Effective engaged weight}$$

$$V_{LS} := C_{sm} \cdot W_T \cdot 0.5 = 1097.5 \text{ kip} \quad \text{shear demand at link-slab in transverse direction}$$

$$As2 := 0.44 \text{ in}^2 \quad \#6 @ 6 \text{ inch spacing at shear interface}$$


$$Fy2 := 60 \text{ ksi}$$

$$W_{ls} := 24 \text{ ft} \quad \text{effective link slab width}$$

$$V_{ni} := 1.0 \left(As2 \cdot \frac{W_{ls}}{6 \text{ in}} \right) \cdot Fy2$$

$$V_{ni} = 1267.2 \text{ kip}$$


$$\frac{V_{ni}}{V_{LS}} = 1.155 > 1.0, \text{ OK}$$



FRP Strengthening of girders to eliminate load posting on the bridge

The current load rating report shows that the E 34th Street Bridge has been reduced to 31 tons. The load rating shows that approach T-beam girders have rating factors of 0.79 and 0.74 for OL2 and EV3, respectively. The lowest rating factors are due to a shear deficiency at 0.6L of approach span.

FRP Properties:



$$\phi_{frp} := 0.85$$

FRP Resistance factor CL. 4.3.1

$$t_f := 0.04 \text{ in}$$

FRP Reinf. thickness/Nominal Laminate thickness

$$w_f := 12 \text{ in}$$

Width of the FRP strip.

$$S_f := 18 \text{ in}$$

Spacing of the FRP strips (set to w_f for continuous reinforcement)

$$n_f := 2$$

Number of fiber plies, each side

$$\alpha_f := 90 \text{ deg}$$

Orientation of the primary fibers with respect to the longitudinal beam axis

$$b_v := 16 \text{ in}$$

width of girder web

$$d_f := 3 \text{ ft} + 4 \text{ in} - 8 \text{ in}$$

Web height strengthened by FRP

Tyfo SCH-41 Composite Properties:

$$f_{fu} := 121 \text{ ksi}$$

Ultimate Design Tensile Strength in Primary Fiber Direction

$$E_f := 11.9 \cdot 10^3 \text{ ksi}$$

Modulus of elasticity (Tensile Modulus) of FRP

$$\epsilon_{fu} := \frac{f_{fu}}{E_f} = 0.01$$

Ultimate strain of fiber rupture (in/in)

Design per AASHTO Guide Specifications for Design of Bonded FRP Systems:

In 34th Ave. Bridge, effective strain will be calculated based on other anchorage condition .

$$\rho_f := \frac{2 \cdot n_f \cdot t_f \cdot w_f}{b_v \cdot S_f} = 0.007$$

$$R_f := \max \left(\min \left(3 \cdot \left(\rho_f \cdot \frac{E_f}{\text{ksi}} \right)^{-0.67}, 1.0 \right), 0.066 \right) = 0.16$$

$$\varepsilon_{fe} := \min (R_f \cdot \varepsilon_{fu}, 0.004) = 0.002$$

$$V_{frp} := \rho_f \cdot E_f \cdot \varepsilon_{fe} \cdot b_v \cdot d_f \cdot (\sin(\alpha_f) + \cos(\alpha_f)) = 66.138 \text{ kip}$$

Design per ICC:

Determine the reduction factor on the ultimate strength of the fiber ply (other method)

$$L_e := \frac{2500 \cdot \text{in}}{\left(\frac{n_f \cdot t_f}{\text{in}} \cdot \frac{E_f}{\text{psi}} \right)^{.58}}$$

$$L_e = 0.9 \text{ in}$$

$$d_{fe} := d_f - 2 \cdot L_e = 30.296 \text{ in} \quad \text{Partially anchored at each end.}$$

$$f'_c := 4 \text{ ksi}$$

Reduction factor accounts for concrete strength or other than 4000 psi. (Bond modification coefficient related to concrete strength).

$$k_1 := \left(\frac{f'_c}{4000 \cdot \text{psi}} \right)^{\left(\frac{2}{3} \right)} \quad k_1 = 1$$

Reduction factor accounts for the type of wrapping scheme. (Bond modification coefficient related to bonded surface configuration).

$$k_2 := \frac{d_{fe}}{d_f} \quad k_2 = 0.947$$

Subject: Initial Seismic and load rating deficiencies evaluation

$$\kappa_V := k_1 \cdot k_2 \cdot \frac{L_e}{468 \cdot \varepsilon_{fu} \cdot \text{in}} = 0.169$$

$$\varepsilon_{fe} := \kappa_V \cdot \varepsilon_{fu} = 0.002$$

$$V_{frp} := \rho_f \cdot E_f \cdot \varepsilon_{fe} \cdot b_v \cdot d_f \cdot (\sin(\alpha_f) + \cos(\alpha_f)) = 69.993 \text{ kip} \quad \text{Shear capacity of FRP}$$

Based on the current load rating, two layers of FRP @ 18 inch should be sufficient to address shear deficiency.

WASHINGTON STATE DEPARTMENT OF TRANSPORTATION
NBI STRUCTURE INVENTORY AND APPRAISAL REPORT
(ENGLISH UNITS)

CD Date: 4/21/2022 Printed on: 4/21/2022
CD Guid: f439ffb4-0148-4e4a-9910-ed839b882bca

IDENTIFICATION				WSBIS DATA			
(1) STATE NAME - WASHINGTON			530	BRIDGE NUMBER			28 34thP-A
(8) STRUCTURE NUMBER			# 085122000000000	BRIDGE NAME			EAST 34TH STREET
(5) INVENTORY ROUTE (ON/UNDER) - On			1 5 1 03234	CUSTODIAN			TACOMA
STATE ROUTE MILEPOST			10.00	CROSSING DESC			EAST 34TH STREET
(2) HIGHWAY AGENCY DISTRICT - OL Region			03	MAIN LISTING FLAG			M
(3) COUNTY CODE 53 - Pierce County		(4) PLACE CODE	70000	SUFFICIENCY RATING			47.92 SD
(6) FEATURES INTERSECTED			PACIFIC TO A ST	CLASSIFICATION			
(7) FACILITY CARRIED			EAST 34TH STREET	(112) NBIS BRIDGE LENGTH			Y
(9) LOCATION			0.2 S JCT I-5	(104) HIGHWAY SYSTEM - Not on the NHS			0
(12) BASE HIGHWAY NETWORK - Not part of network			0	(26) FUNCTIONAL CLASS - Collector			17
(13) LRS INV ROUTE AND SUB ROUTE				(100) DEFENSE HIGHWAY - Not a STRAHNET route			0
(11) LRS MILEPOST				(101) PARALLEL STRUCTURE - Not a parallel bridge			N
(16) LATITUDE		47 Deg 13 Min	58.00 Sec	(102) DIRECTION OF TRAFFIC - 2-way traffic			2
(17) LONGITUDE		122 Deg 25 Min	54.70 Sec	(103) TEMPORARY STRUCTURE - Not Applicable			
(98A) BORDER BR. - Not a border bridge (98B) (99) BORDER BR. SID - Not a border bridge				(105) FEDERAL LANDS HIGHWAY - Not Applicable			0
STRUCTURE TYPE AND MATERIAL				(110) DESIGNATED NATIONAL NETWORK - Not part of network			0
(43) STRUCTURE TYPE MAIN: MATERIAL - Concrete				(20) TOLL - Non-toll structure			3
DESIGN - Arch - deck			111	(21) MAINTENANCE - City or Municipal Highway Agency			04
(44) STRUCTURE TYPE APPR: MATERIAL - Concrete				(22) OWNER - City or Municipal Highway Agency			4
DESIGN - Mixed types			120	(37) HISTORICAL SIGNIFICANCE - On the NRHP			1
(45) NO. OF SPANS IN MAIN UNIT			1	CONDITION			
(46) NO. OF APPROACH SPANS			7	(58) DECK			3
(107) DECK STRUCTURE TYPE - Conc. CIP			1	(59) SUPERSTRUCTURE			5
(108) WEARING SURFACE / PROTECTIVE SYSTEM:				(60) SUBSTRUCTURE			5
(A) TYPE OF WEARING SURFACE - Bituminous			6	(61) CHANNEL AND CHANNEL PROTECTION			N
(B) TYPE OF MEMBRANE - None			0	(62) CULVERTS			N
(C) TYPE OF DECK PROTECTION - None			0	LOAD RATING AND POSTING			
AGE AND SERVICE				(31) DESIGN LOAD - H 20			4
(27) YEAR BUILT			1937	(63) OPER RATING METHOD - Ld Factor (LFR) tons HS20			1
(106) YEAR RECONSTRUCTED			0000	(64) OPERATING RATING			36 T
(42) TYPE OF SERVICE ON - Highway & Pedestrian			5	(65) INV RATING METHOD - Ld Factor (LFR) tons HS20			1
UNDER - Other			0	(66) INVENTORY RATING			21 T
(28) LANES: ON STRUCTURE 2		UNDER STRUCTURE	0	(70) BRIDGE POSTING - Equal or above legal loads			5
(29) AVERAGE DAILY TRAFFIC			4700	(41) STRUCT OPEN, POSTED, CLOSED - Posted for load restrictions			P
(30) YEAR OF ADT 2020		(109) TRUCK ADT	5%	APPRAISAL			
(19) BYPASS, DETOUR LENGTH			1 mi	(67) STRUCTURAL EVALUATION			5
GEOMETRIC DATA				(68) DECK GEOMETRY			2
(48) LENGTH OF MAXIMUM SPAN			243 ft	(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL			N
(49) STRUCTURE LENGTH			485 ft	(71) WATERWAY ADEQUACY			N
(50) CURB OR SIDEWALK: LEFT 5.0 ft		RIGHT	5.0 ft	(72) APPROACH ROADWAY ALIGNMENT			8
(51) BRIDGE ROADWAY WIDTH CURB TO CURB			24.0 ft	(36) TRAFFIC SAFETY FEATURES			0000
(52) DECK WIDTH OUT TO OUT			34.0 ft	(113) SCOUR CRITICAL BRIDGE			N
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)			25 ft	PROPOSED IMPROVEMENTS			
(33) BRIDGE MEDIAN - No median			0	(75) TYPE OF WORK -			351
(34) SKEW 0 Deg		(35) STRUCTURE FLARED	No 0	(76) LENGTH OF STRUCTURE IMPROVEMENT			485 ft
(10) INVENTORY ROUTE MIN VERT CLEAR			99 ft 99 in	(94) BRIDGE IMPROVEMENT COST			\$3,110,000
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR			24 ft 00 in	(95) ROADWAY IMPROVEMENT COST			\$622,000
(53) MIN VERT CLEAR OVER BRIDGE RDW			99 ft 99 in	(96) TOTAL PROJECT COST			\$6,220,000
(54) MIN VERT UNDERCLEAR			0 ft 00 in N	(97) YEAR OF IMPROVEMENT COST ESTIMATE			2022
(55) MIN LAT UNDERCLEAR RT			0.0 ft N	(114) FUTURE ADT			7200
(56) MIN LAT UNDERCLEAR LT			0.0 ft	(115) YEAR OF FUTURE ADT			2037
NAVIGATION DATA				INSPECTIONS			
(38) NAVIGATION CONTROL - Not applicable			N	(90) INSPECTION DATE 06/20		(91) FREQUENCY	24 MO
(111) PIER PROTECTION - Not Applicable				(92) CRITICAL FEATURE INSPECTION:		(93) CFI DATE	
(39) NAVIGATION VERTICAL CLEARANCE			000 ft	(A) FRACTURE CRIT DETAIL - NO -		Month	(A) __/__/__
(116) VERT-LIFT BRIDGE NAV MIN VERT CLR				(B) UNDERWATER INSP - NO -		Month	(B) __/__/__
(40) NAVIGATION HORIZONTAL CLR			0000 ft	(C) OTHER SPECIAL INSP - NO -		Month	(C) __/__/__

Bridge ID	1001	2009	2132	1019	1286	1021	2023	1156	2181	2183	2185	1188	1196
	Structure ID	Bridge Number	Bridge Name	Owner	Cust	County	City	Location	Section	Twnshp	Range	Latitude	Longitude
	08512200	28 34thP-A	EAST 34TH STREET	04	04	27	1280	0.2 S JCT I-5	09	20	03E	47° 13' 58.00"	122° 25' 54.70"

Facilities	1232	1256	1274	7281	7283	1276	1285	1288	1289	1293	1292	2295	7296	Printed Date	Sufficiency Rating: 47.92	
	Feature Intersected	Facilities Carried	Region	Leg1	Leg2	FIPS	Toll	Para	Temp	OPC	NRHP	HAER	LRHP		Status: SD	
	PACIFIC TO A ST	EAST 34TH STREET	OL	2	0	70000	3	N		P	1	4	0		Routine Risk Category: Low Risk	
															Underwater Risk Category:	

Layout	1332	1336	1340	2346	1348	1352	1356	1360	1364	1367	1310	1312	1370	1374	1378	1379	1382	1383	1386	1387	1390	1394	1291	1397
	Year Built	Year Rebuilt	Bridge Length	Screening Length	Maximum Span Length	Lanes On	Curb to Curb Deck Width	Out to Out Deck Width	Sidewalk Left	Sidewalk Right	Skew	Flared	Min Vert Over Deck	Min Vert Under	Vert Code	Min Lat Under Right	Lat Code	Min Lat Under Left	Nav Ctl Code	Nav Vert Clear	Nav Horiz Clear	Nav Vert Lift Clear	Median	Appr Rdwy
	1937	0	485		243	2	24.0	34.0	5.0	5.0	0	N	99' 99"	00' 00"	N	0.0	N	0.0	N	0	0		0	25

Crossing	1432	1433	1434	1435	2440	1445	1451	1453	1457	1463	1467	2410	7479	1483	1484	1485	1486	1487	1489	1490	1354	1491	1495	1499	1413	2441
	On Under	Hwy Class	Service Level	Route Number	Milepost	ADT	Truck %	Year of ADT	Future ADT	Future ADT Year	Linear Referencing System	NBI Bridge	Fed Aid Route #	NHS	BHS	STRAH	FLH	Funct. Class	NTN	Lane Use Direction	Lanes Under	Horizontal Clearance Route Dir	Horizontal Clearance Reverse Dir	Max Vert Clearance Route	Detour	Speed Limit
	1	5	1	03234	10.00	4700	5	2020	7200	2037		Y	3234	0	0	0	0	17	N	2	0	24' 00"			1	30

Design	1532	1533	1535	1536	1538	1541	1544	1545	1546	1547	1548	1549	1550	1551	1552	1553	1554	1555	1556	1585	1588	1590		7565	7557
	Main Span Material	Main Span Design	Appr Span Material	Appr Span Design	Number Main Spans	Number Appr Spans	Service On	Service Under	Deck Type	Wearing Surface	Membrane	Deck Protect	Design Load Code	Oper Rating Method	Oper Rating Tons	Oper Rating Factor	Inv Rating Method	Inv Rating Tons	Inv Rating Factor	State Cd	Border Pct	Border	Border Structure ID	Fed Aid Project No	Design Exemption
	1	11	1	20	1	7	5	0	1	6	0	0	4	1	36	1.01	1	21	0.60						

Load Rating	2587	2588	2589	2590	2591	2592	2593	2594	2597	2598	2595	2596	Waterway/ Prop Imp	7832	7833	7834	7835	7836	7837	7838	7839	7840	7841	1844	1846	1847	2853	2860	1867	1873	2870	1861	1879	2883						
	Type 3	Type 3S2	Type 3-3	NRL	SHV 4	SHV 5	SHV 6	SHV 7	EV 2	EV 3	OL 1	OL 2		Water Type	Flood Pin Infr	Flood Control	Flood Hist	Scour	Matrl	Strmbd	Stabty	Substr	Wtrwy	Obstr	Strmbd	Stabty	Anabrm	Strmbd	Piers In Watr	Type Work	Metl Work	Stru Imp Length	Roadway Width	Cost Per SF	Struct Cost	Rdwy Cost	Engr Cost	Total Cost	Estmt Year	Prop Imp Cost Calc
	1.33	1.33	1.53	1.06	1.07	1.07	1.05	1.03	1.03	0.74	0.87	0.79												35	1	485	27	400	2619	524	2095	5238	2014	Y						
																													475	3110	622	2488	6220	2022						

Inspection Report Types	2920 Inspection	1990 Date	2646 Inspector	2649 Cert No	2654 Co-Inspector
	Routine				
	Fracture Critical				
	Special Feature				
	Underwater				
	UW Interim				

Inspection	Date	Inspector	Cert No	Co-Inspector
Interim	4/4/2022	SJC	G0315	CDN
In Depth				
Damage				
PRM Safety				
SEC Safety				

Inspection	Date	Inspector	Cert No	Co-Inspector
Condition				
Short Span				
Geometric				
Info	4/4/2022	SJC	G0315	CDN
Inventory				

34th Street Bridge April, 2022



Deck view looking west



de

deck view looking east

Please note, the following photographs of the deficiencies found during our interim inspection are not all inclusive of all of the delaminations, spalls, and cracks found during this inspection.



Exposed, rusting reinforcing steel, approx. Sta



Deck delamination with exposed reinforcing steel



Typical delamination in wheel line



Delamination inside wheel lines



deck cracking with delamination



Failed construction joint with associated delaminations



Delamination with exposed reinforcing steel



Failed expansion joints with delaminations



Delamination, spalls, and exposed reinforcing steel.