TSM PP1 IMG_0080 (looking NE) 2013-08-20 14-23-05

TSM PP1 IMG_0081 (looking SE) 2013-08-20 14-23-17

TSM PP1 IMG_0082 (looking SW) 2013-08-20 14-23-43

TSM PP2 IMG_0083 (looking NE) 2013-08-20 14-25-16

TSM PP2 IMG_0084 (looking NW) 2013-08-20 14-25-25

TSM PP2 IMG_0085 (looking SE) 2013-08-20 14-25-32

TSM PP2 IMG_0086 (looking SW) 2013-08-20 14-25-47

TSM PP3 IMG_0087 (looking NE) 2013-08-20 14-27-11

TSM PP3 IMG_0088 (looking NW) 2013-08-20 14-27-19

TSM PP3 IMG_0090 (looking SE) 2013-08-20 14-27-51

TSM PP3 IMG_0089 (looking SW) 2013-08-20 14-27-36

TSM PP4 IMG_0091 (looking NW) 2013-08-20 14-32-23

TSM PP4 IMG_0092 (looking SW) 2013-08-20 14-32-41

TSM PP4 IMG_0093 (looking W) 2013-08-20 14-32-50

TSM PP5 IMG_0094 (looking E) 2013-08-20 14-34-40

TSM PP5 IMG_0095 (looking NE) 2013-08-20 14-34-57

TSM PP5 IMG_0096 (looking SW) 2013-08-20 14-35-10

TSM PP5 IMG_0097 (looking W) 2013-08-20 14-35-20

TSM PP6 IMG_0098 (looking E) 2013-08-20 14-37-25

TSM PP6 IMG_0099 (looking NE) 2013-08-20 14-37-32

TSM PP6 IMG_0100 (looking NW) 2013-08-20 14-37-43

TSM PP7 IMG_0101 (looking NE) 2013-08-20 14-39-02

TSM PP7 IMG_0102 (looking SE) 2013-08-20 14-39-12

Environmental Stewardship Project
Qualitative Ground Survey

Date: 8.20.13. Time: 1:55 pm Year: 1, 2, 3, 4, (5), 6, 7, 8, 9, 10

Site (circle): Yowkwala (YWK), Skookum Wulge (SKW), Squally Beach (SQB), Mowitch (MOW), Jordan/Lower Hylebos Marsh (JOR), Middle Waterway - Simpson (MWS), Middle Waterway – City (MWC), Olympic View (OVRA), Tahoma Salt Marsh (TSM), Swan Creek (SWN)

Steward(s) Present (Volunteer, Staff): D. Podey, M. Henley, V. Rauls. Weather: sunny

Qualitative Observations:

	Hillslope/Riparian	Backshore/Marsh	Beach (below 9 MLLW)
Survival of recent plantings	3/3 doug fir		
Plant Damage by animals (percent damage)	none noted		
Plant Vigor (list species)	OR grape, cottonwood,		
Plant Disease/Stress (percent by species)	drought stress		
Supplemental Planting Needed	not @ this time		
Human Impacts (general)	social trails		
Trash (volume)	minor.		
Vandalism (extent)	none noted		
Perimeter Fencing (condition/maintenance needs)	good		
Goose Exclusion Fencing (condition/maintenance needs)	n/a		
Large Woody Debris (recruitment, presence)	no/yes		
Mulch (quantity needed)	not @ this time		
Erosion/Sedimentation	no significant observations of either		

Vegetation:

Invasive Species and Location:	Reed Canary Grass, thistle, few Blackberry.
Volunteer Species and Location:	fleshy jaumea seen in marsh.

General Vegetation Notes: OK grape spreading freely.

Wildlife Notes (Species observed, other evidence):

Cricket, dog poop.

General Comments:

many social trails.

Photo Points (Record Picture # and Time):

Year: 1, 2, 3, 4, 5, 6, 7, 8, 9, 10

Site: TSM

Date: 8.2013

Site:	P 1 2pm	P 2 2:02pm	P 3 2:04pm	P 4 2:09pm
P 5 2:12pm.	P 6 2:14pm	P 7 2:16pm.	P	P
P	P	P	P	P

TSM.

Adaptive Management Treatment/Solution - Proposed List

Site Code	Description (zone, species/asset, need)	Labor Estimate	Materials Estimate	Priority (i.e. 1,2,3)