

# **Attachment 1**

## **Tables and Figures**

Table 1  
ESP Site Record

ESP Site Record: Yowkwala	
Observational Categories	Dates of Site Visits
Human Impacts	8/6/09
	Yes - Continues to be hang out spot with bonfires and party trash
Erosion	none noted
Weeds	Heavy along immediate shoreline area - butterfly bush, pepperweed, blackberry, scott's broom
Fencing	n/a
Plantings	Low survival of recent plantings due to weather/heat stress
Flora	Beach plants having most success
Fauna	Avian species noted
Photo-documentation	Taken

Table 2  
ESP Site Record

Observational Categories	Dates of Site Visits
Human Impacts	8/6/09
Erosion	Minor trash Point continues to erode due to wave action
Weeds	Few native plants - presently primarily blackberry and ivy
Fencing	Repair of perimeter fencing needed when clearing and plantings are completed
Plantings	Planned for October 2009
Flora	Few native plants
Fauna	Avian species noted
Photo-documentation	Taken

Table 3  
ESP Site Record

ESP Site Record: Squally Beach	
Observational Categories	Dates of Site Visits
Human Impacts	8/6/09
Erosion	Clearing from sign to marsh opening
Weeds	Minor - not significant Minor Blackberry and pepperweed. Knotweed to the north continues to be encroachment concern.
Fencing	Perimeter fencing is good. Wood debris exclusion fencing needs repair (approx. 30')
Plantings	none noted
Flora	All species doing well
Fauna	Avian species noted
Photo-documentation	Taken

Table 4  
ESP Site Record

ESP Site Record: Mowitch		Dates of Site Visits
Observational Categories		8/6/09
Human Impacts	note noted	
Erosion	none noted	
Weeds	Small areas of blackberry, phragmites, and pepperweed.	
Bird's foot trefoil		
Fencing	Needs main gate	
Plantings	none noted	
Flora	Volunteer pickleweed noted	
Fauna	Avian species noted	
Photo-documentation	Taken	

Table 5  
ESP Site Record

<b>ESP Site Record: Jordan</b>	
<b>Observational Categories</b>	<b>Dates of Site Visits</b>
Human Impacts	8/6/09 Minor trash - recreational trail use
Erosion	none noted
Weeds	Blackberry encroachment on E side of trail. Reed canary grass and purple loosestrife are ongoing concerns
Fencing	Platform structures intact
Plantings	none noted
Flora	All species are doing well
Fauna	Beaver evidence. Avian species noted
Photo-documentation	Taken

Table 6  
ESP Site Record

ESP Site Record: Middle Waterway, City	
Observational Categories	Dates of Site Visits
Human Impacts	8/12/09
Erosion	Minor - along roads and high tide line
Weeds	Non-significant
Fencing	Small areas of knapweed, blackberry, nightshade, pampas grass, butterfly bush, white sweet clover
Plantings	Perimeter fencing intact Could use additional riparian plants in areas
Flora	Jaumea spreading.
Fauna	Avian species noted
Photo-documentation	Taken

Table 7  
ESP Site Record

ESP Site Record: Middle Waterway, Simpson	
Observational Categories	Dates of Site Visits
Human Impacts	8/12/09
Erosion	Minimal trash. Vagrant activity noted on the south end of the site near 11th Street
Weeds	none noted
Fencing	minor pea, st. john's wort, blackberry
Plantings	n/a
Flora	50%? Mortality due to weather/heat stress
Fauna	Dry Rose doing well
Photo-documentation	Avian species noted
	Taken



Table 8  
ESP Site Record

<b>ESP Site Record: Olympic View, City/DNR</b>	
<b>Observational Categories</b>	<b>Dates of Site Visits</b>
Human Impacts	8/13/09
Erosion	none noted
Weeds	Some noted on west side of salt marsh entrance
Fencing	Heavy population of invasives along perimeter
Plantings	goose exclusion
Flora	Good condition
Fauna	Recent planting of salt marsh - will need to watch for survivability in spring
Photo-documentation	Rose doing well
	Avian species noted. Rabbits and fish also noted
	Taken

Table 9  
ESP Site Record


ESP Site Record: Tahoma Salt Marsh	
Observational Categories	Dates of Site Visits
Human Impacts	8/12/09
Erosion	Continued vandalism to sprinkler system. Minor trash
Weeds	Some noted associated with logs and mouth
Fencing	Small areas of tansy, nightshade, blackberry, thistle
Plantings	Good condition
Flora	Dry Could use some additional plants on the island. Doing well. Salt marsh plants filling in slowly.
Fauna	Avian species noted. Rabbit
Photo-documentation	Taken

Table 10  
ESP Site Record

ESP Site Record: Swan Creek	
Observational Categories	Dates of Site Visits
Human Impacts	8/19/09
Erosion	Trails established by fisherman, social. Some trash noted at north end and south end.
Weeds	None noted - flow continues to be modified by beaver activity Heavy areas of blackberry and reed canary grass. Minor areas of scott's broom, morning glory, knotweed
Fencing	Fair condition. North fencing recently replaced to deter further dumping
Plantings	Minor damage by beaver.
Flora	Great coverage near stream and channels.
Fauna	Beaver. Avian species noted
Photo-documentation	Taken




# YOWKWALA





# SKOOKUM WULGE





# SQUALLY BEACH





# MOWITCH - HEAD OF HYLEBOS





# JORDAN/LOWER HYLEBOS MARSH







# MIDDLE WATERWAY, CITY





# MIDDLE WATERWAY, SIMPSON





# OLYMPIC VIEW, CITY & WDNR





# TAHOMA SALT MARSH





# SWAN CREEK

